



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5/12/2010 Operator Four Star Oil & Gas API #30-0 39-06596

Property Name RINCON UNIT Well No. 92 Location: Unit G Section 11 Township 26N Range 07W

Well Status(Shut-In or Producing) Tubing 53 Intermediate N/A Casing 48 Bradenhead **

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow _____

Surges _____

Down to Nothing _____

Nothing _____

Gas _____

Gas & Water _____

Water _____

DENIED

BY: Brandon Powell
DATE: 9/10/12 (505) 334-6178

Test required by
11/12/12

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

Oil Cons. Div
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS: The Bradenhead valve will not operate. It is stuck in the open position.

By Bruce Martin
by April E Pohl
(Position)

Witness _____

E-mail address _____