



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7.23.10 Operator Chevron Midcontinent, L.P. API #30-0 39-82376
Property Name RINCON UNIT Well No. 136 Location: Unit A Section 23 Township 27N Range 07W
Well Status (Producing) Tubing 48 Intermediate N/A Casing 94 Bradenhead *

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow _____

Surges _____

Down to Nothing _____

Nothing _____

Gas _____

Gas & Water _____

Water _____

DENIED

BY: Brandon Powell
DATE: 9/10/12 (505) 334-6178

Test required by
11/12/12

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE _____ BRADENHEAD _____ INTERMEDIATE _____

REMARKS: The Bradenhead valve is broken off. Pipe needs to be replaced.

By Bruce Martin
by Spil & Pohl
(Position)

Witness _____

E-mail address _____

Oil Cons. Div
District III

JUL 20 2012