



**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrdd.state.nm.us/ocdd/District/III/3d/stric.htm>**

(submit 1 copy to above address)

Well Status(Shut-In or Producing) Initial PSI: Tubing 45.1 Intermediate X Casing 60.1 Bradenhead 12.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	X	60.1		
10 min	0	X	60.1		
15 min	0	X	60.1		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing X 3sec	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

Oil Cons. Div.
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.5 INTERMEDIATE

REMARKS:

By Randy Culcote

Witness

Caldor Services
(Position)

E-mail address Randy.C@edwards.com