

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No 1004-0137
Expires July 31, 2010

RECEIVED

SEP 21 2012

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

NMNM-03179

6. If Indian, Allottee or Tribe Name

Farmington Field Office

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Burlington Resources Oil & Gas Company LP

3a. Address

PO Box 4289, Farmington, NM 87499

3b. Phone No. (include area code)

(505) 326-9700

7. If Unit of CA/Agreement, Name and/or No

8. Well Name and No

Aztec 3R

9. API Well No.

30-045-30750

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface

Unit E (SWNW), 1800' FNL & 660' FWL, Sec. 14, T28N, R11W

11. Country or Parish, State

San Juan

New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report BP	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The subject well was P&A'd on 8/23/12 per the attached report.

RCVD SEP 26 '12
OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Dollie L. Busse

Title **Staff Regulatory Technician**

Signature

Dollie L. Busse

Date

9/24/12

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Office

SEP 24 2012

FARMINGTON FIELD OFFICE

BY *SM*

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979
Farmington, New Mexico 87499
505-325-2627 *fax: 505-325-1211

Burlington Resources
Aztec #3R

August 23, 2012
Page 1 of 1

1800' FNL and 660' FWL, Section 14, T-28-N, R-11-W
San Juan County, NM
Lease Number: NMNM-03179
API #30-045-30750

Plug and Abandonment Report Notified NMOCD and BLM on 8/22/12

Plug and Abandonment Summary:

Plug #1 pump 64 sxs (75.52 cf) Class B cement inside casing from 1735' mix and pump 10 sxs (11.18 cf); drop 10 RCN balls; continue to mix and pump 54 sxs (63.72 cf) to cover the Pictured Ciffs, Fruitland, Kirtland and Ojo Alamo top.

Plug #2 pump 26 sxs (28.32 cf) Class B cement to top off casing and install P&A marker.

Plugging Work Details:

8/23/12 Road pump truck and equipment to location. Spot in cement equipment. Check well pressures: casing 20 PSI, bradenhead 0 PSI. RU relief lines, blow well down. Pressure test to 300 PSI test good. Spot plug #1. WOC. Dig out wellhead. Fill out and perform Hot Work Permit. Cut off wellhead. Tag cement in annulus at 30' and at surface in casing. Spot plug #2. Install P&A marker. RD and MOL

Ron Chavez, BLM representative, was on location.
Jim Morris, MVCI representative, was on location.