



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3distric.htm](http://emrdr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

RCVD NOV 2 '12
OIL CONS. DIV.
DIST. 3

Date of Test 11-2-12 Operator Devon API #30-0 45-27340

Property Name Pump Mesa SWD Well No. 1 Location: Unit 10 Section 36 Township 31 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 2000 Intermediate 3.6 Casing 10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min	0	3.6	10	0	10
10 min	0	3.6	10	0	10
15 min	0	3.6	10	0	10
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	✓
Gas & Water	✓
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Bradenhead nothing. Intermediate down to nothing in 1 min.

By Phyllis
LEASE OPERATOR Tech
(Position)

Witness Paul Wiede

E-mail address _____