

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 5-23-12 Operator Dugan Production Corp. API # 30-045-05103
Property Name LARGO B FEDERAL Well No 1 Location: Unit A Section 22 Township 24N Range 9W
Well Status (Shut-In or Producing) Initial PSI: _____ Tubing 0 Intermediate 110 Casing 0 Bradenhead* 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interim	
	BH	Int	Csg	Int	Csg
5 minutes	0		0		
10 minutes	0		0		
15 minutes	0		0		
20 minutes	0		0		
25 minutes	0		0		
30 minutes	0		0		

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

BRADENHEAD	INTERMEDIATE
X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

X

INTERMEDIATE _____

REMARKS:

Down hole problems

By

Mike Smeal
Switcher
(Position)

Witness
