NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

(Submit 1 copy to above address)

Oil Conservation Division Aztec District Office 1000 Rio Brazos Road Aztec, NM 87410 (505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm **BRADENHEAD TEST REPORT**

OIL CONS. DIV DIST. 3

MOV 0 1 2012

							MOAGE	COIL	
Date of Test	5/22/12	_ Operator	Dugan Production Corp. API #			30-045-29133			•
Property NameFLO JO			Well No. 5	Location: Unit	0	_Section	1 Township	23N Rar	nge <u>11W</u>
Well Status(Shut-In or Producing) Initial PSI:			Tubing	Intermediate	NA	Casing	A.	Bradenh <u>ead</u>	A
ODENI DD/	/DENHEAD AN		EDIATE TO ATMO	SOUEDE IND	ואוסו ואו	LV EOR 1.	E MINUITEO I	EACH	
OPEN BRA	PRES		EDIATE TO ATM	JOFFIERE IND	IVIDUAL	LIFON	3 MINOTES I	EACH	
Bradenhead Interm			FLOW CHARACTERISTICS						
TIME	BH Int Csg	Int Csg	_	-	BRADE	NHEAD	INTERME	DIATE	
5 mintues	A O	-	Steady Flo	w					
10 minutes	0 0	1	Surges						
15 minutes	8 8		Down to No	othing					
20 minutes	Ø Ø		Nothing		_/				
25 minutes	<u> </u>		Gas				····-		
30 minutes			Gas & Wat	er					
	·	•	Water						
18 b			. (() . (. ()		4				
<u>if braden</u>	<u>nead flowed v</u>	<u>water, cne</u>	ck all of the de	scriptions tr	iat appi	y below:			
	CLEA	₹	FRESH	SALTY	SULFU	IR BI	LACK		
		·			_ **-	·· <u>·</u>	<u> </u>	-	
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE									
REMARKS:			•						
		<u></u>							

498	Witness
Switcher (Position)	

Ву