

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 6-11-12 Operator Dugan Production Corp. API # 30-045-32708
Property Name HERRY MONSTER Well No 90 Location: Unit K Section 11 Township 24N Range 11W
Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate 0 Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0	0	40	0	40	
10 minutes	0	0	40	0	40	
15 minutes	0	0	40	0	40	
20 minutes	0	0	40	0	40	
25 minutes	0	0	40	0	40	
30 minutes	0	0	40	0	40	

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
✓	✓

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By Clay Ekins
Switcher
(Position)

Witness _____