## NEW MEXICO ENERGY, MINERALS • & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

Date of Test	<u>(, -2.1 - 12</u> Operator	Dugan Production Corp.	API #	30-045	-25051		
	•	Well No Location.				24N Rang	је <u>9W</u>
Well Status(Sh	ut-In or <u>Producing)</u> Initial PSI	Tubing 40 Intermedi	ate	_Casing _	30	Bradenh <u>ead</u>	0
TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	PRESSURE  Bradenhead Interm  BH Int Csg Int Csg  0 30 0  0 30	Steady Flow Surges Down to Nothing Nothing Gas Gas & Water Water	FLOW BRADE	CHARACT	TERISTICS INTERME		
<u>If bradenh</u>	ead flowed water, che	eck all of the description	ns that apply	y below	<u>/:</u>		
	CLEAR	FRESHSALTY	SULFU	R	BLACK	_	
5 MINUTE S REMARKS.	SHUT-IN BRADENHI	EAD <u>O</u>	INTERMEDIATE	<u> </u>		<u>.                                    </u>	
·							
Ву	Luis Vasqu Switcher		Witness		·		