NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT



BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

NOV 0 1 2012

Date of Test	(0-//- 2 Operator		Dugan Production	n Corp.	API #	30-045	-26769	
								ip <u>23N</u> Range <u>9W</u>
Well Status(Shu	ut-In or Producin	g) Initial PSI:	Tubing 39	Intermediate		Casing	35.8	Bradenhead 0
							•	
TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes		Interm Int Csg	Steady Flow Surges Down to Nothing Gas Gas & Water	hing	FLOW		TERISTICS	S EACH
	,		Water					
<u>If bradenho</u>	·		ck all of the des					_
5 MINUTE S	HUT-IN	BRADENHE	ad <u>Ö</u>	_ INTE	RMEDIATE			
By Mullmut #110 Switcher (Position)				Witne	ess			