NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT BRADENHEAD TEST REPORT (Submit 1 copy to above address)

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

NOV 0 1 2012

					140 4	O H EOIE
Date of Test .	5-25-/2 Operate	or <u>Dugan Product</u>	ion Corp.	_API# <u>30-</u>	045-29909	
Property Name	DORSEY 1	Well No1	Location: Unit	E_Sec	tion <u>26</u> Township	22N Range 08W
	out-In or Producing) Initial					
				<u> </u>		•
ODEN RRA	DENHEAD AND INTE	DMEDIATE TO ATM	IOSDHERE INDI	VIDHALI V E	OD 15 MINUTES	EACH
OI LIV DIV	PRESSURE	INIEDIATE TO ATIV	OOI TIERE INDI	VIDOALLIT	OK 10 MINOTEO	LACIT
	Bradenhead Interm			FLOW CHAF	RACTERISTICS	
TIME	BH Int Csg Int	Csg		BRADENHE	AD INTERME	DIATE
5 mintues	Ø 175	Steady FI	ow			
10 minutes	8 175	Surges				
15 minutes	ø 195	Down to N	Nothing	-		
20 minutes	de 175	Nothing		Ø		
25 minutes		Gas				
30 minutés		Gas & Wa	ater			
	,	Water				
					_	
<u>If bradenh</u>	ead flowed water,	check all of the d	escriptions th	at apply be	<u>low:</u>	
	CLÉAR -	FRESH	SALTY	SULFUR	BLACK	
						_
5 MINUTE S	SHUT-IN BRADE	NHEAD	INTER	RMEDIATE		
REMARKS:		,				
	 	. 180				•
<u> </u>						
_ · _						
	<u> </u>			·····		
	MI					
Ву	/ Jan		Witne	ss		
	Switc	her				

(Position)