NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

Date of Test	5-09-12	Operator	Dugan Productio	n Corp.	API#	30-045-	31346		
Property Name	CISC	о сом	Well No 91S	_Location: Unit	F	Section _	34 Township	26N Range	∍ <u>13W</u>
Well Status(Sh	nut-In or Producir	ng) Initial PSI:	Tubing 5.5	Intermediate 🔨	YA-	Casing _	5	Bradenhead	<u></u>
OPEN BRA		ND INTERME SSURE	EDIATE TO ATMO	SPHERE INDI		Y FOR		EACH	
TIME	BH Int Cs					NHEAD	INTERME	DIATE	
5 mintues	6 5	5	Steady Flow	,					
10 minutes	0 3	5	Surges	<u></u>					
15 minutes	0 5	;	Down to No	thing					
20 minutes	0 3	5	Nothing		•				٠
25 minutes	0 .	5	Gas	-	-				
30 minutes	0 5	S	Gas & Wate	er					
		1	Water						
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK									
5 MINUTE S		BRADENHE/			. _		-		
	,		•		-				
								<u> </u>	
Ву	Travis	Brector Switcher	, #38	_ Witnes	ss				
Ву	,	brector	, #38-	_ Witnes	SS				