NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170
http //emnrd state nm us/ocd/District III/3distric htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3
NOV 0 1 2012

Date of Test 5-09-12 Operator Dugan Production Corp. API # 30-045-05598

Property Name WEST BISTI UNIT Well No. 157 Location: Unit P Section 36 Township 26N Range 13W

Well Status(Shut-In or Producing) Initial PSI Tubing 300 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

	PRESSURE				
	Bradenhead			Interm	
TIME	BH	Int	Csg	Int	Csg
5 mintues	0		0		
10 minutes	0		0		
15 minutes	0		0		
20 minutes	0		0		
25 minutes	0		0		
30 minutes	0		0		

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

By Travis Boreaton 38

Switcher
(Position)

Witness _____