NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT,

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

Date of Test	5-8	- 12	_Opera	itor	Dugan Production Corp.				API#	30-045	30-045-05651					
Property Nam	eW	EST BIS	TI UN	1IT	Well No.	142	Locatio	n: Unit	M	Section	_28_	Township	26N	Range	13\	Ν
Well Status(S	hut-In o	roducing) Initia	al PSI.	Tubing	75	Interme	edi <u>ate</u>	/A	_Casing	95	· · · · · ·	Braden	h <u>ead</u>	2_	-:47
OPEN BRA	ADENHE	AD ANI		ERME	DIATE ⁻	TO ATM	OSPHEF	RE INDI	VIDUAL	LY FOR	. 15 MII	NUTES	EACH			
	Bradenhead Interm				FLOW CHARACTERISTICS											
TIME	BH I	nt Csg	Int	Csg	•				BRAD	ENHEAD		NTERME	DIATE	_		
5 mintues	0	95				Steady Fl	ow								•	
10 minutes	0	95				Surges								_		
15 minutes	0	95				Down to N	Nothina					.		-		
20 minutes	0	95			/	Nothing	_							-		
25 minutés	0	95			(-	Gas								-		
30 minute's	0	95				Gas & Wa	ater		-	·				-		
		. • •	11	1	•	Water				-				-		
				•							L			-		
lf braden	head flo	owed v	vater,	chec	k all o	f the d	<u>escripti</u>	ons th	at appl	y belov	<u>v:</u>					
		CLEAF	`		FRESH .		SALTY	·	_SULFL	JR	BLACK		-			
5 MINUTE	SHIIT.II	J	RRAF	SENIHE	ND.	\bigcirc		INITES	MEDIAT	E						
REMARKS.	01101-11	•	DIVAL		٠.	-\		IIN I Lair		L						
•																
						· <u>-</u>					_			-		
					-	····								-		
		<u> </u>			-									-		
					· · · ·								 -	-		
Bv	100	- TULS	Ro	بن مع	lan .	÷	, ,	Witnes	ss			•				
,		<u> </u>		cher	+								•	-		
			(Posit													
													•			