

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 6/21/12 Operator Dugan Production Corp. API # 30-045-05799
Property Name WEST BISTI UNIT Well No 106 Location: Unit D Section 19 Township 26N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 115 Intermediate N/A Casing 115 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	0		115			Steady Flow	
10 minutes	0		115			Surges	
15 minutes	0		115			Down to Nothing	
20 minutes	0		115			Nothing	
25 minutes	0		115			Gas	
30 minutes	0		115			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

By Aldo Davila
Switcher
(Position)

Witness _____