## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3 NOV 0 1 2012

Date of Test 6-5-12 Operator			Dugan Production Corp.		API#	30-045-22018		
Property Name	WESTERN I	EDERAL	Well No6	Location. Unit	J	Section	7 Township	26N Range 11W
Well Status(Sho	ut-In or Rroducing)	Initial PSI:	Tubing 5	Intermedia <u>te</u>		_Casing _	Ø	Bradenhead Ø
TIME 5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	PRESS Bradenhead BH Int Csg	URE Interm Int Csg	Steady Flow Surges Down to Not Nothing Gas Gas & Water Water	hing	FLOW	CHARACT	ERISTICS INTERME	
<u>ii pradenn</u>			k all of the des				<u>i</u>	
•	CLEAR	<del> </del>	FRESH	SALTY	_SULFU	₹ <u> </u>	BLACK	-
5 MINUTE S	HUT-IN	BRADENHEA	d <u>Ø</u>	_ INTER	RMEDIATE			
		- A	,					
Ву	- Jh	Switcher (Position)		Witnes	ss			