## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

## http://emnrd state.nm.us/ocd/District III/3distric.htm BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

MOA 0 I 5015 Dugan Production Corp. API# 30-045-22473 Date of Test 5-22/12 Operator Well No. 1 Location. Unit Property Name BLANCO WASH J Section 2 Township 24N Range 9W NA Casing 25 Bradenhead O Well Status(Shut-In or Producing) Initial PSI: Tubing 30 Intermediate OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH **PRESSURE** Bradenhead Interm FLOW CHARACTERISTICS TIME Int Csg Int Csg **BRADENHEAD** INTERMEDIATE 5 mintues Steady Flow 25 10 minutes Surges 25 15 minutes Down to Nothing 25 20 minutes Nothing 25 25 minutes Gas 25 30 minutes Gas & Water Water If bradenhead flowed water, check all of the descriptions that apply below: CLEAR \_\_\_\_\_ FRESH \_\_\_\_ SALTY SULFUR \_\_\_ BLACK **5 MINUTE SHUT-IN** BRADENHEAD INTERMEDIATE REMARKS: Mike Sweat Ву Witness Switcher

(Position)