## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

http://emnrd.state.nm.us/ocd/District III/3distric.htm

NOV 0 1 2012

														. 4 2 20		
Date of Test	5-	72	-12	Operator		Dugan	Produc	tion Corp	n Corp.		30-045-22938					
Property Name		BL	ANCO	WAS	Н	Well No	4	Locatio	n Unit	Α	_Section	2	Township	_24N_R	ange	<u>9W</u>
Well Status(Shut-In or Pro			ducing	Initial PSI:		Tubing	. 70	Interme	edia <u>te</u>	N	_Casing _	0	_Bradenh <u>ea</u>	· /		
OPEN BRAI	DENI		D AND		ERME	DIATE	TO ATN	MOSPHER	RE INC	DIVIDUAL	LY FÒR	15 M	INUTES	EACH		
•	Brad	lenhe	ad	Interm						FLOW	CHARACTERISTICS					
TIME	BH	Int	Csg	Int	Csg	ī				BRADI	ENHEAD		INTERME	DIATE		
5 mintues	0		0				Steady F	low		./						
10 minutes	0		0				Surges						···			
15 minutes	Ó		Ö				Down to	Nothing								
20 minutes	0		0				Nothing									
25 minutes	0		0				Gas									
30 minutes	0		0				Gas & W	ater		,						
							Water									
If bradenh	ead_	flov	ved w	ater,	chec	k all c	of the d	lescripti	ons t	hat appl	y below	<u>/:</u>				
			CLEAR			FRESH		SALTY		SULFU	JR	BLAC	· <	-		
5 MINUTE S REMARKS:	HUT	-IN		BRAD	ENHEA	AD			INTE	ERMEDIATI	E					
							<u> </u>				<del></del>	···········				
· · · · · ·							<del></del>							<del></del>		
									**			····				
Ву			Milr	. (	<b>.</b>				Witn	ess						
-,						<u>/</u>		<del></del>	*****							
	Switcher (Position)															