

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

NOV 01 2012

Date of Test 6-12-12 Operator Dugan Production Corp. API # 30-045-26435  
Property Name BRONZE MEDAL Well No. 1 Location: Unit D Section 3 Township 23N Range 10W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 35 Intermediate \_\_\_\_\_ Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	6		35			
10 minutes	0		35			
15 minutes	0		35			
20 minutes	0		35			
25 minutes						
30 minutes						

**FLOW CHARACTERISTICS**

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

BRADENHEAD	INTERMEDIATE
✓	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Anthony B. 40  
Switcher  
(Position)

Witness \_\_\_\_\_

**OIL CONS. DIV DIST. 3**

NOV 01 2012