NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

											NOV 0 1 2012				012	
Date of Test	<u> 7-</u>	10-	12	_Opera	ator	Dugan	Producti	on Corp.	Corp.		30-045-34524					
Property Name	·	ROA	ADRU	NNE	R	_Well No	92	Location	: Unit	В	_Section	36	Township	24N	Range 11W	
Wëll Status(Sh	ut-In of Producing			Initial PSI.		Tubing	128	Intermed	liate N	<u>la</u>	_Casing .	<u>80</u>)	Bradent	nead O	
OPEN BRA	DENI	HEAD	O AND	TNI	ERME	DIATE	TO ATM	OSPHER	E INDIV	'IDUAL	LY FOR	15 M	INUTES	EACH		
		F	PRESS	URE												
•	, Bradenhead Interm									FLOW	CHARACTERISTICS				•	
TIME	BH	Int	Csg	Int	Csg	7				BRADE	ENHEAD		INTERME	DIATE	- ,	
5 mintues	0				30	_	Steady Flo	w							-	
10 minutes	0				30	_	Surges								_	
15 minutes	0				30		Down to N	othing							_	
20 minutes							Nothing						_		•	
25 minutes							Gas								_	
30 minutes							Gas & Wa	ter							=	
		1			 	_	Water								-	
															-	
<u>If bradent</u>	ead.	flow	<u>red w</u>	ater	, che	ck all c	of the de	scriptio	ns tha	t appl	y below	<u>/:</u>				
		,	>1 C A D			EDECLI		CALTY		01 51	ID.	DI 401	,			
		(CLEAR			- FKESH		SALTY		_SULFU	<u> </u>	BLAC		-		
5 MINUTE S	SHUT	-IN		BRA	DENHE	AD	0		INTERN	MEDIATE	Ē					
REMARKS:													-			
															_	
													-		_	
						-									-	
· · ·															-	
Ву	1<		NV	Se	AM	T .			Witness	5						
					tcher			_	å.	-					-	
				(Posi												