

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX (505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 5-22-12 Operator Dugan Production Corp. API # 30-045-34925
Property Name WOOD DEN Well No 1 Location: Unit L Section 8 Township 22N Range 08W
Well Status(Shut-In or Producing) Initial PSI: Tubing 130 Intermediate _____ Casing 110 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	Ø		110			
10 minutes	Ø		110			
15 minutes	Ø		110			
20 minutes	Ø		110			
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

BRADENHEAD	INTERMEDIATE
✓	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN


BRADENHEAD

Ø

INTERMEDIATE

REMARKS:

By


Switcher
(Position)

Witness
