NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012 Dugan Production Corp. 30-045-26814 Date of Test API# Property Name MARY LOU Well No Location: Unit M Section 32 Township 24N Range 10W Well Status(Shut-In or Producing) Initial PSI: Tubing Intermediate Casing OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH **PRESSURE** Bradenhead Interm **FLOW CHARACTERISTICS** TIME Int Csg Int **BRADENHEAD** INTERMEDIATE 5 mintues Steady Flow 10 minutes Surges 15 minutes Down to Nothing 20 minutes Nothing 25 minutes Gas 30 minutes Gas & Water Water If bradenhead flowed water, check all of the descriptions that apply below: SALTY FRESH SULFUR BLACK **5 MINUTE SHUT-IN BRADENHEAD** INTERMEDIATE REMARKS:

Witness

Ву	W
	C Switcher
	(Position)

100