

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emrod.state.nm.us/ocd/DistrictIII/3district.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 6-12-12 Operator Dugan Production Corp. API # 30-045-28968  
Property Name PAR Well No 1 Location: Unit A Section 11 Township 23N Range 10W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 20 Intermediate \_\_\_\_\_ Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead		Interm	
	BH	Int Csg	Int	Csg
5 minutes	0	20		
10 minutes	0	20		
15 minutes	0	20		
20 minutes	0	20		
25 minutes				
30 minutes				

FLOW CHARACTERISTICS

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

BRADENHEAD	INTERMEDIATE
✓	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By *Michael...* #40  
Switcher  
(Position)

Witness \_\_\_\_\_