

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emr.state.nm.us/ocd/District/III/3distnc.htm>

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 6/15/12 Operator Dugan Production Corp. API # 30-045-31359
Property Name PAUL REVERE COM Well No 95 Location: Unit L Section 22 Township 26N Range 13W
Well Status(Shut-In or Producing) Initial PSI: Tubing 60 Intermediate N/A Casing 23 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		23		
10 minutes	0		23		
15 minutes	0		23		
20 minutes	0		23		
25 minutes	0		23		
30 minutes	0		23		

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS

By Alto Oaxaca Witness _____
Switcher
(Position)