

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 7-12-12 Operator Dugan Production Corp. API # 30-045-31695  
Property Name MARY LOU Well No 90S Location: Unit J Section 32 Township 24N Range 10W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 28 Intermediate 0 Casing 17 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>				<u>17</u>	
10 minutes	<u>0</u>				<u>17</u>	
15 minutes	<u>0</u>				<u>17</u>	
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD	INTERMEDIATE
<u>✓</u>	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

By KENNY SCHAEKE  
Switcher  
(Position)

Witness \_\_\_\_\_