

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3/district.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 5-23-12 Operator Dugan Production Corp. API # 30-045-25919  
Property Name MUDDY MUDDA Well No 1 Location: Unit D Section 21 Township 24N Range 09W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate na Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes	0		0					Steady Flow
10 minutes	0		0					Surges
15 minutes	0		0					Down to Nothing
20 minutes	0		0			X		Nothing
25 minutes	0		0					Gas
30 minutes	0		0					Gas & Water
								Water

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD X INTERMEDIATE \_\_\_\_\_

REMARKS:

Down hole problems

By Mike Sneed  
Switcher  
(Position)

Witness \_\_\_\_\_