

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**
Sundry Notices and Reports on Wells

2005 APR 22 AM 5:44

Lease Number
NMNM-077281**1. Type of Well**

Oil Well

RECEIVED

070 FARMINGTON NM

If Indian, All. or
Tribe Name**2. Name of Operator**

Parwon Operating LLC, c/o David Drake

7. Unit Agreement Name
NE Hogback**3. Address & Phone No. of Operator**

PO Box 5575, Farmington, NM 87499 505-326-7633

8. Well Name & Number
NEHBU #26**9. API Well No.**
30-045-09751**4. Location of Well, Footage, Sec., T, R, M**

1800' FNL and 1980' FEL, Section 10, T-30-N, R-16-W

10. Field and Pool
Horseshoe Gallup**11. County & State**
San Juan County, NM**12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA****Type of Submission**☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment**Type of Action**☒ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☐ Other -☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut off☐ Conversion to Injection**13. Describe Proposed or Completed Operations**

A-Plus Well Service plugged and abandoned this well for Parwon Operating per the following:

3/24/05 RU rig. Well pressures: 0# bradenhead. ND wellhead. NU BOP, test. PU A-plus workstring and round trip a 5.5" casing scraper to 1485'. TIH with tubing and set 5.5" DHS CR at 1454'. Sting out of CR. Circulate 5.5" casing clean with 40 bbls of water. Pressure test 5.5" casing to 500#, held OK.

Plug #1 with CR at 1454', spot 40 sxs Type III cement (51 cf) inside casing above CR up to 1069' to isolate the Gallup perforations and to cover the top.

TOH with tubing. Perforate 2 bi-wire holes at 265'. Circulate bradenhead annulus clean with 20 bbls of water. Shut in well.

3/25/05 Circulate bradenhead annulus clean with 3 bbls of water.

Plug #2 with 90 sxs Type III cement (119 cf) pumped down the 5.5" casing from 265' to surface, circulate good cement out the bradenhead.

Shut in well and WOC. ND BOP. Dig out and cut off wellhead. Tough digging, chip away cement from around wellhead. Found cement at the surface in both the 5.5" casing and in the annulus.

Mix 15 sxs Type III cement to fill casing and then install the P&A marker. RD & MOL.

V. Lucero, BLM, was on location.

SIGNATURE


William F. Clark

Contractor

March 31, 2005

(This space for Federal or State Office use)

APPROVED BY

Title

CONDITION OF APPROVAL, if any:

Date

ACCEPTED FOR RECORD

NMOCD

APR 28 2005

FARMINGTON FIELD OFFICE
BY SW