

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District lil/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test Deloka 15, 03	Operator	Mam Production	_API #30-0	
Property Name dieserilla 3715	"_Well No	Location: UnitS	ection <u>25</u> Townsh	nip <u>34-N</u> Range <u>5-</u> W
Well Status(Shut-In or Producing	) Tubing 65	Intermediate Casin	ng <u>75</u> Brandenh	nead O
OPEN BRADENHEAD AND IN	TERMEDIATE T	TO ATMOSPHERE INDIV	/IDUALLY FOR 15	MINUTES EACH
PRESSURES: TIME INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		Steady Flow		
10 minutes		Surges		
15 minutes		Down to Nothin	g	
20 minutes		Nothing J		
25 minutes		Gas		
30 minutes		Gas & Water		
		Water		
If bradenhead flowed water, check al	l of the description	ns that apply below:	1920	212222
CLEAR FRESH	SALTY	SULFURBLAC	CK Confi	Voy A
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE 2				
REMARKS:				is on I
				9.5 t State
	·			
By Alonzo Harriey	Wit	ness		
Position)	·			