

O': Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-26-03 (Property Name SO. BISTI FEDE		Operator	Operator Four Corners Expl		loration _e API#		30-045-26730			
		DERAL 29	_Well No £o	cation: Unit	Α	Section	ction 29 Township 25		Range 12	:V
Pressure(Shut-	-In or Producing)	Tubing	Intermediate		Casing	424	Bradenhea	ad	70=	
	OPEN BRAD	ENHEAD A	ND INTERMEDIATE	TO ATMOSF	PHERE	INDIVIDU	JALLY FOR	15 MIN	UTES EAC	H
	PRESSURES:				BRADENHEAD		INTERMEDIATE			
TIME	INTERMEDIATE	CASING	-		FLOWE	<u> </u>	FLOWED		_	
5 mintues		0	Steady Flow	<u></u>	W.P				_	
10 minutes		0	Surges				AF		_	
15 minutes		0	Down to Nothing				(23431	6' 'Z	<u>\</u>	
20 minutes		0	Nothing		0		MAY	7 5		
25 minutes			Gas			100 Sec. 200		િ		
30 minutes			Gas & Water			_\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		*		
			Water		···		3	× 22	<u> </u>	
							Marie Comment	منتنست		
If bradenhe	ead_flowed wa	iter, check	all of the description	ns that appl	v belov	v:				
			•			_				
	CLEAR		FRESHSA	LTY	SULFUR	BI	ACK	_		
DEMARKS										
REMARKS:	ROADEN	Venn	BIEW TO	0 # EN	1 15	SECO	NOS LA	EFT		
			BLEW TO	O# ZN	15	SECO	1105 4	FFT	_	
	BRADEN FOR Z			O# ZN	1 15	SECS	NOS 48	FFT	-	
				0 # <i>EN</i>	1 15	SECO	01105 LE	FFT	- 	
	FOR Z	O MINS		O# ZN	1 15	SECO	1105 48	FF	- -	
	FOR Z			₩ Z //	1 15	SECO	1105 48	FFT	- -	