




NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)



BRADENHEAD TEST REPORT
(submit 2 copies to above address)

Date of Test 09/19/03 Operator Nessco, Inc. API # 30-045-13020

Property Name Rudman Federal Well No. 1 Location: Unit E Section 27 Township 25N Range 9W

Well Status (Shut-In or Producing) Tubing 0 Intermediate None Casing -5# Bradenhead 0
SHUT IN

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>None</u>	<u>None</u>	Steady Flow <u>None</u>	<u>None</u>
10 minutes	<u>None</u>	<u>None</u>	Surges <u>None</u>	<u>None</u>
15 minutes	<u>None</u>	<u>None</u>	Down to Nothing <u>-----</u>	<u>-----</u>
20 minutes	<u>None</u>	<u>None</u>	Nothing <u>-----</u>	<u>-----</u>
25 minutes	<u>None</u>	<u>None</u>	Gas <u>None</u>	<u>None</u>
30 minutes	<u>None</u>	<u>None</u>	Gas & Water <u>None</u>	<u>None</u>
			Water <u>None</u>	<u>None</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE None

REMARKS:

No flow at all.

By George L. McDonald
George L. McDonald
Owner/Operator
(Position)

Witness _____