## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

	. ,							
Date of Test	5/14/03 Operator Duga		Production Corp.	API#	30-045-2658	7	<u>.</u>	
Property Name	JIM THORPE	Well No	o1 Location:	Unit G	Section 03	Township 23N	Range	10W
Well Status(Sho	ut-In or Producing)	Tubing 35	Intermediate NA	Casing	36	Bradenhead	0	-
		NHEAD AND INT	ERMEDIATE TO A				JTES E	ACH
718.45	PRESSURES:				NHEAD	INTERMEDIATE		
TIME	INTERMEDIATE C	ASING		FLOWE	:U	FLOWED	-	
5 mintues			Steady Flow		·		-	
10 minutes			Surges				-	
15 minutes		<del> </del>	Down to Nothing			NA	-	
20 minutes			Nothing					
25 minutes			Gas	· · · · · · · · · · · · · · · · · · ·			-	
30 minutes		<u> </u>	Gas & Water		<u></u>		_	
			Water				-	
If bradenh	ead flowed wa	ter, check all	of the descriptio	ns that apply	y below:			
	CLEAR_	FRESH	SALTY	SULFU	RBLAC	K		
5 MINUTE S	SHUT-IN B	RADENHEAD		INTERMEDIATE		210 10 20 m		
REMARKS:						M 10 13 (1) (1) (3)		
						1 VIAY 2002		
,								
<del> </del>					(3)	East, and a second		
Ву	Mall	Town	$\overline{)}$	Witness	V3)	Q0/13/2	7	
38	- 000	Switcher				The same of the sa	-	
		Position)	·					