

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 5/14/03 Operator Dugan Production Corp. API # 30-045-05646  
Property Name WEST BISTI UNIT Well No. 136 Location: Unit O Section 26 Township 26N Range 13W  
Well Status(Shut-In or Producing) \_\_\_\_\_ Tubing N/A Intermediate N/A Casing N/A Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD \_\_\_\_\_

INTERMEDIATE \_\_\_\_\_

REMARKS:

N/A

By

44

Jimmy Fane

Switcher

(Position)

Witness \_\_\_\_\_

