OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District111/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	7-16-03	Operator	ROBERT L. BAYLESS	API #30-0	45-21346	
Property Name			4 Location: Unit K			6N Range 18W
Well Status (Shut-In or Producing) Tubing O Intermediate O Casing SO Brandenhead O						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING	ř	8	RADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	0	80	Steady Flow			
10 minutes	6	8'0	Surges	 		
15 minutes	0	80	Down to Nothing			
20 minutes			Nothing			
25 minutes			Gas		28.00	THE 20 THE
30 minutes			Gas & Water			20, 73 (3)
			Water			
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENDHEAD O INTERMEDIATE						
REMARKS:						
By William Schnedow Witness						
By William Schnedow Witness Pemper						
(Position)						