



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emfird.state.nm.us/ocd/District 3/district.htm](http://emfird.state.nm.us/ocd/District%203/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 6-11-03 Operator CHAPARRAL ENERGY API #30-0 45-21378

Property Name NAVAJO TRIBE Well No. AR#4 Location: Unit I Section 27 Township 26N Range 18W

Well Status (PUMPING Shut-In or Producing) Tubing 80-95 Intermediate N.A. Casing 90 Bradenhead 110

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>90</u>	Steady Flow	
10 minutes		<u>90</u>	Surges	
15 minutes		<u>90</u>	Down to Nothing	<u>X</u>
20 minutes			Nothing	
25 minutes			Gas	<u>X</u>
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

BRADENHEAD BLEW DOWN IN 30 SECONDS OR LESS &  
BLEW A FEW DROPS OF WATER (CLEAR), PROBABLY CONDENSATION.

By Jim Hicks

Witness \_\_\_\_\_

AGENT  
(Position)

