



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmrnd.state.nm.us/ocd/District III/3distric.htm](http://emmrnd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 7-8-03 Operator MERRION OIL & GAS CORP. API #30-0 45-25679

Property Name SERENDIPITY COM Well No. 1 Location: Unit J Section 26 Township 26N Range 13W

Well Status(Shut-In or Producing) Tubing 46 Intermediate NA Casing 48 Bradenhead Q(JSTM)

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:	
	INTERMEDIATE	CASING
5 minutes	<u>NA</u>	<u>48</u>
10 minutes	<u>NA</u>	<u>48</u>
15 minutes	<u>NA</u>	<u>48</u>
20 minutes	<u>NA</u>	<u>48</u>
25 minutes	<u>NA</u>	<u>48</u>
30 minutes	<u>NA</u>	<u>48</u>

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		<u>NA</u>
Surges		
Down to Nothing		
Nothing	<u>Nothing</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

This is a pumping well with a compressor pulling gas. Test
taken while compressor down and waiting on mechanic. Bradenhead has been
plumbed above ground with 1" pipe and valve that has been closed and
plugged all year. When opened B.H. hispered dry gas for 2 or 3 seconds.

By [Signature]

Witness _____

Contract Pumpers
(Position)

