

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 5-14-3 Operator Dugan Production Corp. API # 30-045-05720
Property Name WEST BISTI UNIT Well No. 119 Location: Unit N Section 20 Township 26N Range 13W
Well Status(Shut-In or Producing) Producing Tubing 100 Intermediate Casing TSTM Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>	<u>0</u>	Steady Flow		
10 minutes			Surges		
15 minutes	<u>/</u>	<u>/</u>	Down to Nothing		
20 minutes	<u>/</u>	<u>/</u>	Nothing	<u>X</u>	
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

By *Jimmy Lee*
44 Switcher
(Position)

Witness _____

