

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 5-14-3 Operator Dugan Production Corp. API # 30-045-05750  
Property Name WEST BISTI UNIT Well No. 114 Location: Unit L Section 20 Township 26N Range 13W  
Well Status(Shut-In or Producing) Producing Tubing 100 Intermediate        Casing TSTM Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>	<u>0</u>	Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing	<u>X</u>	
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR        FRESH        SALTY        SULFUR        BLACK       

**5 MINUTE SHUT-IN** BRADENHEAD        INTERMEDIATE       

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By                       
44                       
Switcher  
(Position)

Witness                     

