

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 6-03-03 Operator Dugan Production Corp. API # 30-045-29434
Property Name GALWAY Well No. 90 Location: Unit B Section 13 Township 26N Range 13W
Well Status(Shut-In or Producing) _____ Tubing _____ Intermediate _____ Casing 10# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

By

Bob Hill

Witness _____

27

Switcher

(Position)

