

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 6-03-03 Operator Dugan Production Corp. API # 30-045-30310
Property Name DOMe NAV 13-26-13 Well No. 1R Location: Unit I Section 13 Township 26N Range 13W
Well Status (Shut-In or Producing) Tubing Intermediate Casing 0# Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

NO BRADENHEAD, WELL SHUT IN FOR WELL
WORKOVER.

Bob Gill

Witness _____

27

Switcher
(Position)

