

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 4-22-03 Operator Dugan Production Corp. API # 30-045-27126  
Property Name LEAH MARIE Well No. 1 Location: Unit C Section 23 Township 26N Range 12W  
Well Status(Shut-In or Producing) Tubing 0# Intermediate        Casing 20# Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>	<u>20#</u>	Steady Flow		
10 minutes	<u>0</u>		Surges		
15 minutes	<u>0</u>		Down to Nothing		
20 minutes	<u>0</u>		Nothing	<u>0</u>	
25 minutes	<u>0</u>		Gas		
30 minutes	<u>0</u>		Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR        FRESH        SALTY        SULFUR        BLACK       

**5 MINUTE SHUT-IN** BRADENHEAD        INTERMEDIATE       

REMARKS:

NO BRADENHEAD, P.T. ON LOCATION.

By 27 Switcher (Position) Witness       

711981