

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-28-03 Operator Dugan Production Corp. API # 30-045-30093
Property Name MITZI COM Well No. 90 Location: Unit G Section 23 Township 26N Range 12W
Well Status(Shut-In or Producing) Tubing 0 Intermediate Casing 7 1/2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>	<u>7 1/2</u>	Steady Flow		
10 minutes	<u>0</u>		Surges		
15 minutes	<u>0</u>		Down to Nothing		
20 minutes	<u>0</u>		Nothing	<u>0</u>	
25 minutes	<u>0</u>		Gas		
30 minutes	<u>0</u>		Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

P.T. ON LOCATION.

By

Bob Hill

Witness

27

Switcher

(Position)