

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 4-29-03 Operator Dugan Production Corp. API # 30-045-05932  
Property Name BLACKROCK FEDERAL B Well No. 1 Location: Unit L Section 08 Township 26N Range 11W  
Well Status(Shut-In or Producing) \_\_\_\_\_ Tubing 0# Intermediate \_\_\_\_\_ Casing 62# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>	<u>62#</u>	Steady Flow		
10 minutes	<u>0</u>		Surges		
15 minutes	<u>0</u>		Down to Nothing		
20 minutes	<u>0</u>		Nothing	<u>0</u>	
25 minutes	<u>0</u>		Gas		
30 minutes	<u>0</u>		Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

HAS P.T. ON LOCATION.

By

Bob Hill

Witness \_\_\_\_\_

27

Switcher

(Position)