

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test $4-9-93$	Benson-Monting Corporator Drilling Corp		06075
Property Name Wininger State Well 1			
Well Status(Shut-In or Producing) Tubin	g/50 Intermediate/50	Casing Brander	nhead &
OPEN BRADENHEAD AND INTERMED	IATE TO ATMOSPHERE	INDIVIDUALLY FOR 1	5 MINUTES EACH
PRESSURES: TIME INTERMEDIATE CASI	NG	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Steady Flo	ow	
10 minutes	Surges_		
15 minutes	Down to 1	Nothing	22
20 minutes	Nothing_	MAY	No.
25 minutes	Gas	200	
30 minutes	Gas & Wa	ater	4. 9
	Water	<u> </u>	
If bradenhead flowed water, check all of the des	criptions that apply below:		a di
CLEAR FRESH SALT	Y SULFUR	BLACK	
5 MINUTE SHUT-IN BRADENHEAD	INTERMEDIATE	<u> </u>	
REMARKS: 10 braden head 1	nesent Jusi	t hole in	side out
Casing			
By Ollimak	Witness		.09
Pumper		ſ	25 41490
(Position)		Ö	25 0317641498
			031.