

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 10-29-03	Operator	Maralex Reso	2000 API #30-0 45.	18754
Property Name Zicks Well No. 2 Location: Unit M Section 9 Township Kange 11W				
Well Status(Shut-In or Producing) Tubing Intermediate Casing Brandenhead				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		Steady Flow		
10 minutes		Surges		
15 minutes		Down to Nothing		
20 minutes		Nothing		
25 minutes		Gas		
30 minutes		Gas & Water		
Water				
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH	SALTY	SULFUR	BLACK	
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE				
REMARKS:				
By Marken Dode Witness_				
By Marken Dode Witness				