OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD

AZTEC, NM 87410

 $(505)\ 334\text{-}6178\ FAX:\ (505)\ 334\text{-}6170$ $\text{http:}\\ \text{htm:}\\ \text{distric.htm}$

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

	<u>5-8-03</u> Open					A
Property Name	KRAUSE PC & FC	Weff No. 1	Location: Unit	C Section 2	Township 26	N Range 11W
Well Status (Shut-In or Producing) Tubing 200 Intermediate Casing 6 Brandenhead 8						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow	**************************************		
10 minutes			Surges	 		
15 minutes			Down to Nothing			
20 minutes			Nothing	\times	ļ	
25 minutes			Gas		29	3037
30 minutes			Gas & Water			
			Water			003 5
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR	FRESH	SALTY_	SULFUR	BLAC	K_SIMEL	21.11.20.2
5 MINUTE SHUT-IN BRADENDHEAD INTERMEDIATE						
REMARKS:						
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			All and heart to a second device device about the second second as a least the second		······································	
<u></u>						
By Albert Husla Witness						
e de la compansa de l	Position)	_				