

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
Aztec District Office  
1000 Rio Brazos Road  
Aztec NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://nemrds.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)


Date of Test 7-8-03 Operator CORDILLERA ENERGY, INC. API# 30-045-05995

Property Name DAVIS Well No. 2 Location: Unit 0 Section 5 Twp 26N Range 8W

Pressure (Shut-in or Producing) \_\_\_\_\_ Tubing GO Intermediate \_\_\_\_\_ Casing 100 Bradenhead 9757M

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>100</u>	Steady Flow <u>NO FLOW</u>	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

REMARKS:

By [Signature] Witness \_\_\_\_\_  
[Signature]  
(Position)