

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-03 Operator Dugan Production Corp. API # 30-045-24905
Property Name ELWOOD P DOWD Well No. 2 Location: Unit P Section 10 Township 24N Range 09W
Well Status(Shut-In or Producing) Tubing 11 Intermediate Casing 11 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>11</u>	Steady Flow	<u>0</u>	
10 minutes		<u>11</u>	Surges	<u>0</u>	
15 minutes		<u>11</u>	Down to Nothing	<u>0</u>	
20 minutes			<u>Nothing</u>		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK


5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Producing H₂O



By

C.E. Harris #49

Witness

49

Switcher

(Position)