OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District111/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-/-03 Operator ROBERT L. BAYLESS, PRODUCER LLC API #30-0 45-06441					
Property Name	САМРВЕ	LE Welf No. 1-	18 Location: Unit M	Section 18 Township	27N Range 8W
Well Status (Shut-In or Producing) Tubing 176			6 Intermediate 1) A	Casing 192 Brandenhead	<u> </u>
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	<u>NA</u>	192	Steady Flow	Nothing	NA
10 minutes		192	Surges		,
15 minutes	« 	192	Down to Nothing		
20 minutes			Nothing		
25 minutes			Gas		10 /4 11 × 10 × 20
30 minutes			Gas & Water		000000000000000000000000000000000000000
			Water		007 2708
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN BRADENDHEAD INTERMEDIATE					
REMARKS:					
well on - Tubing Less than Line Pressure					
	\overline{Q}	21			
By Daril Howar Witness Plompel					
	(Positi	on)			