OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	e of Test <u> </u>			AP1 #30-0 45-21459		
Property Name	HAMMON	DWell No	55 Location: Unit F	Section 26	Township2	7N Range 8W
Well Status (Sh	ut-In or Producing	Tubing /8	Intermediate	_Casing <u>59</u>	Bradenhead/	2
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	NA	59	Steady Flow	/\/	othing	NA
10 minutes		59	Surges			
15 minutes		59	Down to Nothing			
20 minutes			Nothing			
25 minutes			Gas	****	200072	7777
30 minutes			Gas & Water		60 00 B	
			Water	<u></u>	30	23 3
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD & INTERMEDIATE MA						
REMARKS:	Ħ					
7 d 7 d 7 d 7 d 7 d 7 d 7 d 7 d 7 d 7 d						
						
	D. 1 41	10,000	3.04			
Ву	Pumper	visor ,	Witness			
_	(Positio	on)				