OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-5-03	Operator <u>M&G Drilli</u>	ing Company	AP1 #30-0	45-21734	
Property Name	MARRON	Well No. 4	6A Location: Unit E	Section 23	Township2	7N Range 8W
Well Status (Sh	ut-In or Producing	Tubing / O	Intermediate NA	Casing 37	Bradenhead	0
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING		1	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
.5 minutes	NA	37	Steady Flow		Vothing	NA
10 minutes		37	Surges-)	
15 minutes		37	Down to Nothing	· · · · · · · · · · · · · · · · · · ·	\rightarrow	
2 0 minutes			Nothing .		(
25 minutes			Gas		257312	720-
30 minutes			Gas & Water		007	
			Water		<u></u>	03 (2)
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD SINTERMEDIATE NA						
REMARKS:						
						
By	Davil 1 Pumper	Ywor w	'itness			
	(Positio	on)				